


NEW SOURCE
Forklift Parts

FAX: 1-562-691-2970

contact@newsourcedforkliftparts.com

PICK UP AT
1280 W. LAMBERT RD, UNIT C
BREA, CA 92821
MON – FRI – 9AM – 5PM

 **1-844-244-1144**

<p>DC015 Toyota 4Y 7FGCU 20/25/30/32</p>  <p>8FGCU 15~32 + 8FGU15~32 TY19030-78151-71</p>	<p>DC022 Toyota 5R Point Set</p>  <p>TY 19100-78051-71</p>	<p>DC026 Toyota 5K</p>  <p>TY 19030-78120-71</p>	<p>DC027 Toyota 8 Series</p>  <p>TY19040-78150-71</p>
<p>DC012 Mitsubishi 4G63/64</p>  <p>MB MD326637</p>	<p>DC019 Mitsubishi 4G63/64</p>  <p>MB MD169418</p>	<p>DC024 Mitsubishi 4G52/54</p>  <p>MB MM115552</p>	
<p>DC013 Nissan H20-II/25 K21/25</p>  <p>NI22100-50K10</p>	<p>DC014 Nissan H20 Point Set</p>  <p>NI 22100-K7201</p>	<p>DC020 Nissan H20 Crew On Cap</p>  <p>NI 22100-00H11</p>	<p>DC021 Nissan Z24</p>  <p>NI 22100-87K15 NI 22100-20H11</p>
<p>DC010 GM Vortec 4.3L V-6</p>  <p>HY 1374322</p>	<p>DC016 GM Vortec 4.3L V-6</p>  <p>HY 1559695</p>	<p>DC017 GM 3.0L 4 Cyl</p>  <p>HY 1331330</p>	<p>DC020-B Nissan H20 Clip On Cap</p>  <p>NI 22100-00H11</p>
<p>DC011 Mazda 2.0L</p>  <p>HY 1361849 YT 5059605-91</p>	<p>DC018 Mazda 2.2L</p>  <p>HY 1554030 YT 5800470-16</p>		

All manufacturers logos, names, descriptions and numbers are for reference purposes only and do not imply they are original or genuine parts or that we are an OEM supplier. Prices subject to change without notice.