

<p>BI1527 Mazda 2.2L</p>  <p>HY 1527571</p>	<p>BI1331 GM 3.0 + 4.3L Fits DC010+DC017</p>  <p>HY 1331331</p>	<p>BI1564670 GM 4.3L V-6 Fits DC016</p>  <p>HY 1578521</p>	<p>BI1584523 Hyster/Yale VX</p> <p><i>New</i></p>  <p>YT 5800572-03</p>	<p>BI177230 4G63 and 4G64</p>  <p>MB MD177230</p>
<p>BI91H20 Nissan K21/25</p>  <p>MB 91H20-02930 NI 22448-AR215</p>	<p>BI326638 4G63 and 4G64</p>  <p>MB MD 326638 CL 925969</p>	<p>BI90919 Toyota 4Y</p>  <p>TY 80919-76002-71</p>	<p>TO011PR With Internal Resistor</p>  <p>HY 1324278 NI 22433-00H00 TY 80919-76023-71</p>	<p>BI22100 Nissan H20II/K21 Fits Distributor 22100-50K10</p> 
<p>MD001 Mazda+Mitsubishi</p>  <p>YT 9019538-09 HY 1326536</p>	<p>MD002 Mitsubishi</p>  <p>CL 918892 MB MD611384</p>	<p>MD003 Mitsubishi+Nissan</p>  <p>MB MD619224</p>	<p>MD005 Toyota 4Y</p>  <p>TY 89620-32020-71</p>	<p>MD006 Electronic Ignition</p>  <p>Petronix 1943</p>
<p>YA017 Condensor</p>  <p>TY 80099-76036-71</p>	<p>MD607394 Point Set for Mitsubishi</p>  <p>MB MD602103</p>	<p>26060 Point Set for Komatsu or Toyota</p>  <p>TY 19145-76001-71 KO 19145-41010</p>	<p>BIRE Resistor for Ignition Coil</p> 	<p>Ignitor Signal</p>  <p>TY 19251-76001-71</p>

All manufacturers logos, names, descriptions and numbers are for reference purposes only and do not imply they are original or genuine parts or that we are an OEM supplier. Prices subject to change without notice.