

**NEW SOURCE**  
Forklift Parts

FAX: 1-562-691-2970

contact@newsourcedforkliftparts.com

**PICK UP AT**  
**1280 W. LAMBERT RD, UNIT C**  
**BREA, CA 92821**  
**MON – FRI – 9AM – 5PM**

 **1-844-244-1144**

<p>RT001 <b>Mazda 2.0L</b></p>  <p><b>HY 1326395</b></p>	<p>RT002 <b>Mitsubishi 4G63/64 Nissan H20II - K21/25</b></p>  <p><b>MB MD618262 NI 22157-55K10</b></p>	<p>RT003 <b>GM 3.0 L</b></p>  <p><b>HY 1334403</b></p>	<p>RT005 <b>Mitsubishi 4G32/52/54 4G63/64</b></p>  <p><b>CL 909353 MB MD611850</b></p>	<p>RT007 <b>Daewoo Hercules</b></p>  <p><b>DW D700682</b></p>	
<p>RT008 <b>GM 4.3L-V6</b></p>  <p><b>TY 19102-U3160-71</b></p>	<p>RT009 <b>Toyota 4Y</b></p>  <p><b>TY 19102-76009-71</b></p>	<p>RT010 <b>Nissan A15/ H20</b></p>  <p><b>NI 22157-23G15</b></p>	<p>RT011 <b>GM 4.3L-V6</b></p>  <p><b>HY 1566459 TY 19102-U3330-71</b></p>	<p>RT013 <b>Nissan 6 Cyl</b></p>  <p><b>NI 22157-52H20</b></p>	
<p>YA013 <b>Continental Engine</b></p>  <p><b>CL 850726</b></p>	<p>RT016 <b>Toyota 5K</b></p>  <p><b>TY 19102-76008-71</b></p>	<p>RT017 <b>Hyster FT/Yale VX</b></p>  <p><b>HY 1554034 YT 5800470-19</b></p>	<p>RT018 <b>Toyota 4P, 5R and 5P</b></p>  <p><b>TY 19102-76004-71</b></p>	<p>RT019 <b>Toyota 4P</b></p>  <p><b>TY 19102-76002-71</b></p>	<p>RT020 <b>Toyota 6Cyl</b></p>  <p><b>TY 19102-76005-71</b></p>

All manufacturers logos, names, descriptions and numbers are for reference purposes only and do not imply they are original or genuine parts or that we are an OEM supplier. Prices subject to change without notice.